

RexXer EVO

Available service-functions of the different ECU-types

Release: July 2016 - © by RexXer Tuning GmbH



RexXer EVO Service-Functions											
BRAND	ECU-Type	ECU ID	Read/Write ECU	Read/Clear error codes; CEL's	Firmware Info	TPS reset	Reset autoadaptive parameters	APS reset	CO trimming	Quickshifter reset	Reset Service Due light
Adiva	Magneti Marelli MIU										
Aprilia	Magneti Marelli MIU										
	Magneti Marelli IAW 5AM								*		
	Magneti Marelli IAW 5DM								*		
	Magneti Marelli IAW 7SM								*		
BMW*	BOSCH BMSK ME9								*		
Derbi	Magneti Marelli MIU										
Ducati	Magneti Marelli 15M								*		
	Magneti Marelli IAW 59M										
	Magneti Marelli IAW 5AM										
	Magneti Marelli IAW 7SM								*		
	Conti VDO M3C								*		
	Mitsubishi MELCO								*		
Gas Gas	Magneti Marelli IAW 15P								*		
Gilera	Magneti Marelli IAW 15P								*		
	Magneti Marelli IAW 5AM										
	Magneti Marelli MIU										
KTM	Keihin								*		
KVN	Magneti Marelli IAW 15P								*		
Malaguti	Magneti Marelli MIU										
	Magneti Marelli IAW 15P								*		
Moto Guzzi	Magneti Marelli IAW 15RC								*		
	Magneti Marelli IAW 15M								*		
	Magneti Marelli IAW 5AM										
	Magneti Marelli IAW 5AM										
	Magneti Marelli MIU										
MV Agusta	Magneti Marelli IAW 5SM								*		
	Magneti Marelli IAW 7BM								*		
Peugeot	Magneti Marelli MIU										
Piaggio	Magneti Marelli MIU										
Triumph	Keihin								*		
Vespa	Magneti Marelli MIU										
Voxan	Magneti Marelli IAW 15RC								*		

 Availabel
 Not available

RexXer Tuning GmbH | Astheimer Str. 41 | 65428 Rüsselsheim (Germany) ** This function is not supported by the ECU!
 Fon: +49 (0) 6142 / 793971-203 | Fax: +49 (0) 6142 / 793971-80 | Email: info@rexser.eu | Web: www.rexxer.eu